## **Practice 1**

- 1. Create a 3D Model (single solid body) of the TOOL HOLDER as shown.
- 2. Produce an engineering drawing based on the part. On the drawing:
  - (a) Add 3 orthographic views (hidden details not required).
  - (b) Indicate clearly the angle of projection you are using.

